

# RECALL NOTICE

Marker Recalls 2017-2018 Kingpin 10 and 13 Touring bindings toe parts.



**Hazard:** The Pin in the toe piece can break under rare circumstances. This can lead to reduced release/retention and can result in a fall hazard.

**Recalled Products:** 2017-2018 Kingpin 10 and 13 Touring bindings with serial numbers in the range seen below:



With this serial number on the heel, a Marker Authorized Retailer can confirm if your binding is affected or not. If your serial number is in the range listed below, you should replace the toe pieces.

Kingpin 10  
serial # 337804 - 418632

Kingpin 13  
serial # 337798 - 411728



Toe pieces with these logo treatments are affected by the recall



Toe pieces with these logo treatments are **not** affected by the recall



**Remedy:** Stop using these bindings and return them to a Marker Authorized Retailer to determine if they are covered by this recall. Toe pieces of recalled bindings will be replaced at no charge. Skiers should bring their boots to be sure their bindings are adjusted correctly.

For additional information, call Marker customer service at 1-888-273-4791 Monday through Friday 9:00 a.m. to 5:00 p.m., or send an email to [kingpin.exchange@markervolkl.com](mailto:kingpin.exchange@markervolkl.com), or visit [www.markercanada.com](http://www.markercanada.com).

\* Post Until March 31, 2019